


METAL MC RANGE


MC-05 & MC-10 INSTALLATION GUIDE

MC-05 & MC-10 Metal Clip Set




INSTALLATION STEPS Self tapping method


- 1** Drill hole through support frame and fit MC-F5 or MC-F10




- 2** Mark panel with MC-CP5




- 3** Drill panel on centre mark



- 4** Self tapping screw fit MC-M5 into panel



- 5** Exploded cutaway view of installed clip set




MORE INFO: SETOUT GUIDE TD-02, 09, 12. PRODUCT SHEET MC-05

METAL MC RANGE


MC-05 & MC-10 INSTALLATION GUIDE

MC-05 & MC-10 Maxi Metal Clip Set




INSTALLATION STEPS Screw fix method


- 1** Drill hole through support frame and fit MC-F5 or MC-F10



- 2** Mark panel with MC-CP5



- 3** MC-M5 screw fixed to panel



- 4** Exploded cutaway view of installed clip set

