

NOTE: Connection Strip must be installed during framing stage.



Pro Clima NZ Limited Freephone: 0800 PRO CLIMA (776 254) P0 Box 925 CBD Phone: 04 589 8460 Frax: 04 589 8461 Frax: 04 589

© This drawing is the property of pro clima and must not be copied with out permission. This drawing is a Guideline only. Thermal and hygrothermal performance should match specific design, materials and climate requirements. These can be confirmed by hygrothermal analysis using software eg WUFI.