

Acoustical Testing Laboratory



TESTING
NVLAP LAB CODE 200291-0
Accredited by the National Voluntary
Laboratory Accreditation Program for
the specific scope of accreditation.

Page 1 of 5

TEST REPORT

for

Speedfloor Ltd.

16B Ormiston Rd. Auckland, New Zealand 2016 Hamish Coubray / 64 9 3034825

Impact Sound Transmission Test

ASTM E 492 – 09 (2016)e1 / ASTM E 989 = 18

On

Speedfloor 8" (200mm) Joist Floor-Ceiling Assembly
Overlaid with 3-1/2 Inches (90mm) of Normal Weight Concrete,
and Porcelain Tile over 6mm AcoustiCork Underlayment
1.5"x2" Hat Channel, a Single Layer of 1/2 Inch Type C Gypsum Board
With 3 Inches of Mineral Wool Insulation

Report Number: NGC 7020085_R1

Assignment Number: G-1631

Test Date: 06/15/2020

Report Reissue Date: 10/02/2020

Submitted by:

Anthony J. Rivers
Test Technician

Reviewed by:

Robert J. Menchetti Director

The results reported above apply to specific samples submitted for measurement. No responsibility is assumed for performance of any other specimen. The laboratory's accreditation or any of its test reports in no way constitute or imply product certification, approval, or endorsement by NVLAP, NIST or any agency of the Federal Government. This report may not be reproduced except in full, without written approval of the laboratory.

1650 Military Road • Buffalo, NY 14217-1198 (716) 873-9750 • Fax (716) 873-9753 • www.ngctestingservices.com



Acoustical Testing Laboratory



TESTING
NVLAP LAB CODE 200291-0
Accredited by the National Voluntary
Laboratory Accreditation Program for
the specific scope of accreditation.

NGC 7020085_R1 Speedfloor Ltd. 10/02/2020 Page 2 of 5

Revision Summary:

Date	SUMMARY
Approval Date: 07/24/2020	Original issue date: 07/24/2020 Original NGCTS report: NGC 7020085
Reissue Date: 10/02/2020	Report #: NGC 7020085_R1 The report was revised to fix a typographical error.

The results reported above apply to specific samples submitted for measurement. No responsibility is assumed for performance of any other specimen. The laboratory's accreditation or any of its test reports in no way constitute or imply product certification, approval, or endorsement by NVLAP, NIST or any agency of the Federal Government. This report may not be reproduced except in full, without written approval of the laboratory.



Acoustical Testing Laboratory



TESTING
NVLAP LAB CODE 200291-0
Accredited by the National Voluntary
Laboratory Accreditation Program for
the specific scope of accreditation.

Report Number:

NGC 7020085_R1

Page 3 of 5

Test Method:

This test method is in accordance with American Society for Testing and Materials Standard Test Method for Laboratory Measurement of Sound Transmission Through Floor-Ceiling Assemblies Using the Tapping Machine - Designation: E 492-09 (2016)e1 / E 989-18.

The uncertainty limits of each tapping machine location met the precision requirements of section A1.4 of ASTM E 492-09 (2016)e1.

Specimen Description:

Speedfloor 8" (200mm) Joist floor-ceiling assembly overlaid with, according to client, 3-1/2 Inches (90mm) of Normal Weight concrete, Porcelain Tile over 6mm AcoustiCork Underlayment, 1.5" x 2" Hat Channel and a layer of 1/2" Type C gypsum board, with 3 inches of Mineral wool insulation.

The test specimen was a floor assembly and was observed to consist of the following: All weights and dimension are averaged:

- 1 layer of, Porcelain Tile. The tile was adhered to the 6mm AcoustiCork underlayment using thin set mortar, and grouted with Spectralock Pro Grout. Measured thickness: 8.89 mm (0.35 in.). Measured weight: 19.43 kg/m² (3.98 PSF)
- 1 layer of, 6mm AcoustiCork underlayment. The underlayment was adhered to the concrete slab using Mapei Ultrabond ECO350 adhesive. The adhesive was applied using a 0.06 mm x 0.06 mm x 0.03 mm (1/16 in. x 1/16 in. x 1/16 in.) Square-Notch Trowel. Measured thickness: 6.10 mm (0.24 in.). Measured weight: 1.17 kg/m² (0.24 PSF)
- 1 layer of, 90mm (3-1/2 in.) Normal Weight concrete. Measured weight: 213.59 kg/m² (43.75 PSF)
- According to the client, Speedfloor 8" (200mm) joists. Measured weight: 6.01 kg/m² (1.23 PSF)
- l layer of, 76.2 mm (3 in.) Mineral Wool insulation. Sample weight: 3.61 kg/m² (0.74 PSF)
- 1.5" x 2 in. Hat Channel. The channel was spaced 406.4 mm (16 in.) o.c and was attached perpendicular to the joist. Measured weight of the channel: 0.82 kg/m² (0.17 PSF)
- 1 layer of 12.70 mm (1/2 in.) Type C gypsum board. The Gypsum board was attached to the Hat channel with 31.8 mm (1-1/4 in.) Type S screws spaced 203.2 mm (8 in.) o.c. Measured weigh: 9.28 kg/m² (1.90 PSF)

The overall weight of the test assembly is: 253.91 kg/m² (52.01 PSF)

The perimeter of the test frame was sealed with a rubber gasket and a sand filled trough.

The test frame was structurally isolated from the receiving room.

Specimen size:

3657.6 mm x 4876.8 mm (12 ft. x 16 ft.)

Conditioning:

Minimum 24 hours at 70°F, 55% R.H

Test Results:

The results of the tests are given on pages 4 and 5 of the report.

The results reported above apply to specific samples submitted for measurement. No responsibility is assumed for performance of any other specimen. The laboratory's accreditation or any of its test reports in no way constitute or imply product certification, approval, or endorsement by NVLAP, NIST or any agency of the Federal Government. This report may not be reproduced except in full, without written approval of the laboratory.



Laboratory



Accredited by the National Voluntary Laboratory Accreditation Program for the specific scope of accreditation.

Test Report:	_R1		Date:	6/11/2020	Page 4 of 5	
Specimen Size	[m²]:	17.8				
Source room				Receiving roo	m	
					Volume [m³]:	124
Rm Temp [°C]: 22					Rm Temp [°C]:	22
Humidity [%]: 55					Humidity [%]:	66
mpact Insulati	ion Class IIC	dB1:	53			
Sum of Unfavorable		30				
Max. Unfavorable [6	at	400	Hz	
Frequency	L	L2	d	Corr.	u.Dev.	ΔLn
[Hz]	[dB]	[dB]	[dB/s]	[dB]	[dB]	
80	63	62.9	32.99	0.1		2.18
100	59	58.1	33.38	0.9		1.56
125	59	60.5	23.10	-1.5		0.97
160	61	63.1	17.85	-2.1	2	0.78
200	60	62.8	16.36	-2.8	1	0.81
250	62	64.3	16.44	-2.3	3	0.71
315	63	65.7	16.61	-2.7	4	0.38
400	64	66.2	17.90	-2.2	6	0.60
500	60	61.8	19.77	-1.8	3	0.41
630	58	60.1	20.46	-2.1	2	0.48
	56	57.1	21.59	-1.1	1	0.45
800		56.9	20.36	-1.9	1	0.50
800 1000	55	30.9	20.00	-1.5		
	55 51	52.8	20.67	-1.8		0.39
1000	1					0.39
1000 1250	51	52.8	20.67	-1.8		
1000 1250 1600	51 44	52.8 45.8	20.67 21.88	-1.8 -1.8	2	0.49
1000 1250 1600 2000	51 44 42	52.8 45.8 42.4	20.67 21.88 24.69	-1.8 -1.8 -0.4	2 5	0.49 0.55
1000 1250 1600 2000 2500	51 44 42 44	52.8 45.8 42.4 44.1	20.67 21.88 24.69 27.51	-1.8 -1.8 -0.4 -0.1	2 5	0.49 0.55 0.39

The results reported above apply to specific samples submitted for measurement. No responsibility is assumed for performance of any other specimen. The laboratory's accreditation or any of its test reports in no way constitute or imply product certification, approval, or endorsement by NVLAP, NIST or any agent of the U.S. Government. This report may not be reproduced except in full, without written approval of the laboratory.

1650 Military Road • Buffalo, NY 14217-1198 (716) 873-9750 • Fax (716) 873-9753 • www.ngctestingservices.com



Laboratory



Accredited by the National Voluntary Laboratory Accreditation Program for the specific scope of accreditation.

Normalized impact sound pressure level


Test: ASTM E 492 - 09 (2016) / ASTM E 989 - 18

Page 5 of 5

Test Report: NGC7020085_R1 Test Date: 6/11/2020 Specimen Size [m²]: 17.8

Impact Insulation Class IIC [dB]: 53

Frequency	Ln			
[Hz]	[dB]			
80	63			
100	59			
125	59			
160	61			
200	60			
250	62			
315	63			
400	64			
500	60			
630	58			
800	56			
1000	55			
1250	51			
1600	44			
2000	42			
2500	44			
3150	44			
4000	39			
5000	30			
* Due to biologica deti				



Due to high insulating value of specimen, background levels limit results at these frequencies.

= Normalized Sound Pressure Level, dB

The results reported above apply to specific samples submitted for measurement. No responsibility is assumed for performance of any other specimen. The laboratory's accreditation or any of its test reports in no way constitute or imply product certification, approval, or endorsement by NVLAP, NIST or any agent of the U.S. Government. This report may not be reproduced except in full, without written approval of the laboratory.

> 1650 Military Road • Buffalo, NY 14217-1198 (716) 873-9750 • Fax (716) 873-9753 • www.ngctestingservices.com