



| | |
|--------------------------|---|
| Construction | Luxury Vinyl Tile |
| Plank Size | 241.3 x 1516.8mm |
| Tiles per Carton | 6pcs / 2.196m ² |
| Total Weight | 9050g/m ² |
| Wearlayer Thickness | 0.55mm |
| Total Thickness | 5.0mm |
| Surface Protection | High Performance PU |
| Finish | Embossed in Register Mantel Oak 8594 and Vintage Steel 0143 only Embossed |
| Bevel | 4-sided micro-bevel |
| Micro Scratch Resistance | ≤ MSR-A1 (EN 16094) ≤ MSR-B1 (EN 16094) |
| Slip Resistance | R10 (DIN 51130) |
| Electrical Propensity | <2kV (EN 1815) |
| Fire Rating | CRF > 11.0kW/m ² (ISO 9239-1) |
| Acoustic Insulation | 4dB (EN 10140-3) |
| Dimensional Stability | ≤0.15% (ISO 23999) |
| Thermal Resistance | 0.021 (m ² *K/W) (ISO 12667) |
| Indoor Air Quality | FloorScore® A+ Emissions Eurofins Gold Certified |
| Underfloor Heating | Suitable, max 27°C |
| Residual Indentation | < 0.1mm (EN ISO 24343-1) |
| Colour Fastness | > 6 Grade (ISO 105-B02) |
| Classifications | Class 23 Domestic Heavy / Class 33 Commercial Heavy/ Class 42 Industrial Medium |
| Warranties | LVT Warranty 20 Year Residential Warranty 10 Year Commercial Warranty |
| Environmental | Greentag Certified Environmental Product Declaration GREENGUARD Gold Certification Declare ISO 9001, ISO 45001, ISO 14001 |
| Installation | Please contact Gilt Edge Industries for all adhesive and installation instructions. NB: If recommended adhesive is not used, claims will not be accepted. Must be laid in accordance with AS/NZ Installation Standards. |

- For samples, range and warranty details please contact us on 0800 377 753 or belgotex.co.nz
- Specifications are based on averages from manufacturing processes and may vary within normal industry tolerances.
- This product is intended for use solely as an indoor floor covering and is not recommended or sold for any other purpose.
- Use entryway systems outside each entrance to prevent dirt, sand, grit and other substances from being tracked onto floor.
- **Rubber Migration:** Rubber migration (also known as Plasticiser Migration) is a condition that can cause vinyl to discolour. It is caused by rubber or latex products, eg rubber or latex-soled slippers, shoes and rubber backed mats, coming to contact with the vinyl over a constant period of time. It is neither a manufacturing nor an installation fault and therefore is not covered by our warranties.