Case Study: Viking Dec-K-ing





VIEW THE OCEAN ON A ROBUST, BUT MORE IMPORTANTLY, WATERTIGHT MEMBRANE.

DEC-K-ING ENJOYS THE SEA VIEWS – APARTMENT, MT MAUNGANUI

CHALLENGE: THE ROOF OF AN UPMARKET MOUNT MAUNGANUI APARTMENT SERVES AS A WONDERFUL VIEWING PLATFORM OVERLOOKING THE PACIFIC OCEAN FROM 6 FLOORS UP. BUT BY EARLY 2009, THE APARTMENT'S TIRED BUTYL RUBBER MEMBRANE ROOF WAS BEGINNING TO OXIDIZE - A CONDITION MORE COMMONLY KNOWN AS "CHALKING-OFF".

Not only was this old butyl struggling with the intense UV, the membrane (being black) had a propensity to become extremely hot; putting undue pressure on the air-conditioning requirements (and therefore energy costs) of the building. Additionally, the messy, black butyl powder from this chalking-off was beginning to rub off onto the apartment owners (and their guests) feet when they went onto the roof to enjoy the view.

The owners, The Body Corporate, had installed some artificial grass on top of the butyl to alleviate these issues. Despite marginal success, this was acknowledged as a bit of an "apologetic" strategy – certainly not inkeeping with the quality and location of the building.

Solution

The head of the Body Corporate contacted a local Bay of Plenty Viking Membrane Approved Applicator for suggestions as to where she could find an attractive membrane system that was sufficiently durable to withstand New Zealand's tough climatic and UV conditions.

The Applicator immediately proposed Viking Dec-K-ing and put her in touch with the Viking Roofspec Territory Manager. The Territory Manager explained that a Viking Dec-K-ing Membrane system not only possessed the above properties but was also:

- BRANZ Appraised;
- Heat-welded at its seams for maximum watertightness;
- Possessing a propensity to heat-up a lot slower than other deck surfaces;
- Embossed surface for maximum grip;
- Mesh reinforced for puncture resistance;

...she knew her quest to find the ultimate decking waterproofing solution had come to an end.

The Viking Approved Applicator faced several challenges. The first one being the weather. Being winter time, Viking's Technical Specialist insisted that once the butyl rubber had been removed and disposed of, the porous concrete substrate would need to be coated with Aquaguard 101 to seal its surface. This would prevent the need for expensive down-time to dry out the substrate after each rainfall during the installation period.

But before they could apply the sealant, they faced the challenge of having to smooth the

Auckland Office

80 Alexander Crescent, Otara PO Box 14-541, Panmure Auckland 1741, New Zealand

Christchurch Office 2 Nazareth Avenue, Middleton PO Box 9117, Tower Junction

Christchurch 8149, New Zealand

T. 0800 729 799 F. 0800 729 788 info@vikingroofspec.co.nz www.vikingroofspec.co.nz



Taking care of detail

Case Study: Viking Dec-K-ing



extremely rough texture of the concrete. If not dealt with prior to laying, this rough texture would show through the surface of the membrane.

Result

Once the substrate had been diamondground and then sealed with Aquaguard 101, the application team successfully installed approximately 500 m2 of Viking Dec-K-ing (between periods of appalling weather).

The Body Corporate members were delighted with their wonderful new roof which allowed

them to entertain guests and view the ocean on a robust, but more importantly, watertight membrane; the aesthetics of which are inkeeping with the quality and location of the building.

Viking Full System Warranty

The apartment was also eligible for a Viking Full System Warranty due to the size of the roof deck. A Full System Warranty is one document covering both materials and workmanship for 20 years. The Body Corporate's knowledge that the materials supplier would warrant both the materials and installation – coordinated in the one document for 20 years (no matter what happened to the application company during this period), gave them great peace of mind. The buck would stop with the supplier until 2029.

Auckland Office

80 Alexander Crescent, Otara PO Box 14-541, Panmure Auckland 1741, New Zealand Christchurch Office 2 Nazareth Avenue, Middleton PO Box 9117, Tower Junction Christchurch 8149, New Zealand T. 0800 729 799 F. 0800 729 788 info@vikingroofspec.co.nz www.vikingroofspec.co.nz

