



TESTING
NVLAP LAB CODE 200291-0
Accredited by the National Voluntary
Laboratory Accreditation Program for
the specific scope of accreditation.

Page 1 of 5

TEST REPORT

for

Speedfloor Ltd.

16B Ormiston Rd. Auckland, New Zealand 2016 Hamish Coubray / 64 9 3034825

Sound Transmission Loss Test

ASTM E 90 – 09 (2016) / E 413 – 16

On

Speedfloor 8" (200mm) Joist Floor-Ceiling Assembly
Overlaid with 3-1/2 Inches (90mm) of Normal Weight Concrete,
and 44 oz. Carpet and Foam Rubber Underlayment
with Furring Channel, a Single Layer of 1/2 Inch Type C Gypsum Board

Report Number: NGC 5020077 R1

Assignment Number: G-1631

Test Date: 06/29/2020

Report Reissue Date: 10/05/2020

Anthony J. Rivers

Test Technician

Reviewed by:

Submitted by:

Robert J. Menchetti

Director

The results reported above apply to specific samples submitted for measurement. No responsibility is assumed for performance of any other specimen. The laboratory's accreditation or any of its test reports in no way constitute or imply product certification, approval, or endorsement by NVLAP, NIST or any agency of the Federal Government. This report may not be reproduced except in full, without written approval of the laboratory.





TESTING
NVLAP LAB CODE 200291-0
Accredited by the National Voluntary
Laboratory Accreditation Program for
the specific scope of accreditation.

NGC 5020077_R1 Speedfloor Ltd. 10/05/2020 Page 2 of 5

Revision Summary:

| Date | SUMMARY | |
|---------------------------|---|--|
| Approval Date: 07/24/2020 | Original issue date: 07/24/2020 Original NGCTS report: NGC 5020077 | |
| Reissue Date: 10/05/2020 | Report #: NGC 5020077_R1 The report was revised to fix a typographical error. | |

The results reported above apply to specific samples submitted for measurement. No responsibility is assumed for performance of any other specimen. The laboratory's accreditation or any of its test reports in no way constitute or imply product certification, approval, or endorsement by NVLAP, NIST or any agency of the Federal Government. This report may not be reproduced except in full, without written approval of the laboratory.





TESTING
NVLAP LAB CODE 200291-0
Accredited by the National Voluntary
Laboratory Accreditation Program for
the specific scope of accreditation.

Report Number:

NGC 5020077_R1

Page 3 of 5

Test Method:

This test method conforms explicitly with the American Society for Testing and Materials Standard Test Method for Laboratory Measurement of Airborne Sound Transmission Loss of Building Partitions

Specimen Description:

Speedfloor 8" (200mm) Joist floor-ceiling assembly overlaid with, according to client, 3-1/2 Inches (90mm) of Normal Weight concrete, 44 oz. Carpet over Foam Rubber Underlayment, Furring Channel and a layer of 1/2" Type C gypsum board.

The test specimen was a floor assembly and was observed to consist of the following: All weights and dimension are averaged:

- 1 layer of 44 oz. Carpet. The carpet was floating on the Foam Rubber underlayment. Measured weight of 2.73 kg/m² (0.56 PSF).
- 1 layer of Foam Rubber Underlayment. The underlayment was floating on the Normal Weight concrete. The measured thickness of the underlayment was 9.65 mm (0.38 in.), Measured weight of 2.34 kg/m² (0.48 PSF).
- 1 layer of, 90mm (3-1/2 in.) Normal Weight concrete. Measured weight: 213.59 kg/m² (43.75 PSF)
- According to the client, Speedfloor 8" (200mm) joists. Measured weight: 6.01 kg/m² (1.23 PSF)
- Furring. The channel was spaced 406.4 mm (16 in.) o.c and was attached perpendicular to the joist. Measured weight of the channel: 0.73 kg/m² (0.15 PSF)
- 1 layer of 12.70 mm (1/2 in.) Type C gypsum board. The Gypsum board was attached to the Furring channel with 31.8 mm (1-1/4 in.) Type S screws spaced 203.2 mm (8 in.) o.c. Measured weigh: 9.28 kg/m² (1.90 PSF)

The overall weight of the test assembly is: 234.68 kg/m² (48.07 PSF)

The perimeter of the test frame was sealed with a rubber gasket and a sand filled trough.

The test frame was structurally isolated from the receiving room.

Specimen size:

3657.6 mm x 4876.8 mm (12 ft. x 16 ft.)

Conditioning:

Minimum 24 hours at 70°F, 55% R.H

Test Results:

The results of the tests are given on pages 4 and 5 of the report.

The results reported above apply to specific samples submitted for measurement. No responsibility is assumed for performance of any other specimen. The laboratory's accreditation or any of its test reports in no way constitute or imply product certification, approval, or endorsement by NVLAP, NIST or any agency of the Federal Government. This report may not be reproduced except in full, without written approval of the laboratory.





Accredited by the National Voluntary Laboratory Accreditation Program for the specific scope of accreditation.

| iest: ASTM E | 90 - 09 (2016) / A | STM E 413 - 16 | 5 | | | | |
|--|--|--|--|--|---|--------|--|
| Test Report: NGC 5020077 R1 | | | | Page 4 of Date: 6/29/2020 | | | |
| Specimen Size | | 17.8 | | Dale. | 0/25/2020 | | |
| Source room | [111-]. | 17.0 | | | Desciulna rec | | |
| Volume [m³]: 86 | | | | Receiving room Volume [m³]: 124 | | | |
| Rm Temp [°C]: 25 | | | Volume [m³]: 124 Rm Temp [°C]: 25 | | | | |
| Humidity [%]: | | | | | | | |
| | ission Class ST | CIADI | 52 | | riditiidity [/6]. | 30 | |
| | | | 32 | | | | |
| Sum of Unfavorable | | 12 | -4 | 105 | 11- | | |
| Max. Unfavorable [| at an artist of the second | 8 | at | 125 | Hz | | |
| Frequency | STL | L1 | L2 | d | Corr. | u.Dev. | ΔSTL |
| [Hz] | [dB] | [dB] | [dB] | [dB/s] | [dB] | [dB] | |
| 80 | 35 | 100.9 | 68.5 | 31.2 | 2.5 | | 2.26 |
| 100 | 27 | 103.0 | 79.6 | 25.9 | 3.6 | | 5.65 |
| 125 | 28 | 102.3 | 77.8 | 21.3 | 3.6 | 8 | 1.01 |
| 160 | 36 | 104.5 | 73.2 | 16.6 | 4.8 | 3 | 2.20 |
| 200 250 | 42 45 | 104.2 | 67.1 | 16.1 | 4.9 | | 0.85 |
| 250 315 | 45 | 100.4 | 60.6 | 15.7 | 5.2 | | 2.15 |
| 400 | 50 | 97.9 96.1 | 55.6 51.1 | 16.0 | 5.7 | 1 | 0.99 |
| 400 | | 96.5 | 46.7 | 18.0 18.8 | 5.0 4.2 | ' | 0.67 |
| 500 | | | 40.7 | 1 10.0 | 4.2 | 1 | 1.61 |
| 500 | 54 57 | | | 1 | I . | | 0.00 |
| 630 | 57 | 96.9 | 44.0 | 20.3 | 4.2 | 1 | 0.86 |
| 630 800 | 57 60 | 96.9 95.8 | 44.0 40.0 | 20.3 21.4 | 4.2 4.2 | | 1.35 |
| 630 800 1000 | 57 60 59 | 96.9 95.8 92.0 | 44.0 40.0 37.2 | 20.3 21.4 20.1 | 4.2 4.2 4.2 | | 1.35 1.45 |
| 630 800 1000 1250 | 57 60 59 65 | 96.9 95.8 92.0 91.5 | 44.0 40.0 37.2 30.7 | 20.3 21.4 20.1 20.3 | 4.2 4.2 4.2 4.1 | | 1.35 1.45 1.30 |
| 630 800 1000 1250 1600 | 57 60 59 65 71 | 96.9 95.8 92.0 91.5 91.7 | 44.0 40.0 37.2 30.7 24.5 | 20.3 21.4 20.1 20.3 21.6 | 4.2 4.2 4.2 4.1 3.8 | | 1.35 1.45 1.30 1.16 |
| 630 800 1000 1250 1600 2000 | 57 60 59 65 71 75 | 96.9 95.8 92.0 91.5 91.7 94.6 | 44.0 40.0 37.2 30.7 24.5 22.6 | 20.3 21.4 20.1 20.3 21.6 24.7 | 4.2 4.2 4.2 4.1 3.8 2.9 | | 1.35 1.45 1.30 1.16 1.92 |
| 630 800 1000 1250 1600 | 57 60 59 65 71 | 96.9 95.8 92.0 91.5 91.7 | 44.0 40.0 37.2 30.7 24.5 22.6 23.4 | 20.3 21.4 20.1 20.3 21.6 24.7 27.7 | 4.2 4.2 4.2 4.1 3.8 2.9 2.6 | | 1.35 1.45 1.30 1.16 1.92 2.70 |
| 630 800 1000 1250 1600 2000 2500 | 57 60 59 65 71 75 75 | 96.9 95.8 92.0 91.5 91.7 94.6 95.8 | 44.0 40.0 37.2 30.7 24.5 22.6 | 20.3 21.4 20.1 20.3 21.6 24.7 | 4.2 4.2 4.2 4.1 3.8 2.9 | | 1.35 1.45 1.30 1.16 1.92 |

The results reported above apply to specific samples submitted for measurement. No responsibility is assumed for performance of any other specimen. The laboratory's accreditation or any of its test reports in no way constitute or imply product certification, approval, or endorsement by NVLAP, NIST or any agent of the U.S. Government. This report may not be reproduced except in full, without written approval of the laboratory.

1650 Military Road • Buffalo, NY 14217-1198 (716) 873-9750 • Fax (716) 873-9753 • www.ngctestingservices.com



Laboratory



NVLAP LAB CODE 200291-0

Page 5 of 5

Accredited by the National Voluntary Laboratory Accreditation Program for the specific scope of accreditation.

Sound Transmission Loss Test Data

Test: ASTM E 90 - 09 (2016) / ASTM E 413 - 16


Test Report: NGC 5020077 R1


Test Date: 6/29/2020

Specimen Size [m2]: 17.8

Sound Transmission Class STC = 52 dB

| Frequency | STL | ΔSTL |
|-----------|------|------|
| [Hz] | [dB] | |
| 80 | 35 | 2.26 |
| 100 | 27 | 5.65 |
| 125 | 28 | 1.01 |
| 160 | 36 | 2.20 |
| 200 | 42 | 0.85 |
| 250 | 45 | 2.15 |
| 315 | 48 | 0.99 |
| 400 | 50 | 0.67 |
| 500 | 54 | 1.61 |
| 630 | 57 | 0.86 |
| 800 | 60 | 1.35 |
| 1000 | 59 | 1.45 |
| 1250 | 65 | 1.30 |
| 1600 | 71 | 1.16 |
| 2000 | 75 | 1.92 |
| 2500 | 75 | 2.70 |
| 3150 | 77 | 3.18 |
| 4000 | 79 | 3.52 |
| 5000 | 77 | 3.94 |





= Sound Transmission Loss, dB

= Uncertainty for 95% Confidence Level

The results reported above apply to specific samples submitted for measurement. No responsibility is assumed for performance of any other specimen. The laboratory's accreditation or any of its test reports in no way constitute or imply product certification, approval, or endorsement by NVLAP, NIST or any agent of the U.S. Government. This report may not be reproduced except in full, without written approval of the laboratory.

> 1650 Military Road • Buffalo, NY 14217-1198 (716) 873-9750 • Fax (716) 873-9753 • www.ngctestingservices.com